



## DISCONTINUED ITEMS AND REPLACEMENTS

Part #	Description	Obsolted On	Discontinued On	Replacement Parts	Notes
9A	Safety Chain		05/2019	9, 10, 10A	Different specs - show options to customer to see if one will work w/ their application.
11	Drawbar Eye	10/2017	07/2020	4	Can show other bolt on eyes with same ID & specs.
<b>12L</b>	Tow Hook-Left	10/2017			<b>Limited to Quantities on hand (4/20/22) - No replacement</b>
<b>12R</b>	Tow Hook-Right	10/2017			<b>Limited to Quantities on hand (4/20/22) - No replacement</b>
<b>107</b>	Drawbar Eye	10/2017			<b>Limited to Quantities on hand (4/20/22)</b> - No direct replacement - 107 had 2-3/8" ID & used with 3" OD tubing - can show other eyes with same ID & specs.
126	Bolt on Eye		04/26/18		No direct replacement - 126 had 2-3/8" ID - can show other bolt on eyes with same ID & specs.
203	Weld on Eye	10/2017	11/27/17		No direct replacement - 203 was offset w/ 2 -1/2" ID - can show other eyes with same ID & specs.
2300B	Coupling	02/2018	07/09/18	370B	Direct replacement w/ same mounting pattern & bottom mount air service chamber; Different body & latch.
306	Drawbar Eye	05/2014	04/21/22	304	Can show other eyes with same ID & specs.
360*	Coupling	02/2018	07/2019	2300/370	Direct replacement w/ same mounting pattern. Take into consideration pushrod length. *60PK discontinued.
410 Series	Swivel Eye	06/2014	12/2015	405 Series	Make sure 405 series works w/ customers application and current front end. They may/may not need to replace front end.
470	Coupling			2400	Direct replacement w/ same mounting pattern. Different body & latch.
				2400EL	Direct replacement w/ same mounting pattern. (2400EL includes extended life latch direct-inject lubrication ports); Different body & latch. Premalloy.
				100-4	Direct replacement w/ same mounting pattern; Different body & latch.
470H	Coupling		07/2019	2400H/2400HEL	Direct replacement w/ same mounting pattern. Different body & latch.
				2400HEL	Direct replacement w/ same mounting pattern. (2400HEL includes extended life latch direct-inject lubrication ports); Different body & latch.
				100-4H	Direct replacement w/ same mounting pattern; Different body & latch.
590L	Coupling	01/2017	10/2017	580	Same mounting pattern.
				2200L/2200ELL	Same mounting pattern. Both options have low profile latches.
				690L	Make sure 690L works w/ customers application. If customer has to have a drop pintle coupling.
60PK	Repair Kit	02/2018	07/2019		Parts Kit (for use with 360 - also discontinued)
690R*	Coupling	11/2016	10/2017	690L	Same body & mounting pattern. Handle on left side *690RRK discontinued (690LRK not for use w/ 690R. Voids all warranty)
690T*	Coupling		11/2016	690L	Same body & mounting pattern. Handle on left side *690LRK discontinued (690LRK not for use w/ 690T. Voids all warranty)
690RKK	Repair Kit				Repair Kit for 690R Coupling (also discontinued)
690TRK	Repair Kit				Repair Kit for 690T Coupling (also discontinued)
703	Jack Screw	10/19/2018			703 no longer available for individual sale - Available in the 700RK Repair Kit
707	Jack Brass Nut	10/19/2018			707 no longer available for individual sale - Available in the 700RK Repair Kit
770	Coupling	01/03/2018	04/04/18	570	Similar style coupling w/ low profile latching system & rear mount air chamber. Mounting pattern is slightly different
<b>780</b>	Coupling	10/2017		2880	<b>2880 has same bolt pattern. Limited to Quantities on hand (4/20/22)</b>
781	Trip Handle		04/21/22		Component in 880 & 880RK - No replacement
782	Latch		04/21/22		Component in 880 & 880RK - No replacement
783	Lever		04/21/22		Component in 880 & 880RK - No replacement
790	Coupling	10/2017			
790RK	Repair Kit		04/02/20	N/A	Repair Kit for 790 (discontinued repair kit components listed below) 791, 792,793, 793B, 793B-1, 794Z, 795Z, 796, 797, 798, 793CP
880*	Coupling	07/2019	01/2020	2880	Direct replacement w/ same mounting pattern *880RK limited to quantity on hand
<b>880RK*</b>	Repair Kit			N/A	<b>Limited to Quantities on hand (4/20/22) - Repair Kit for 880 Coupling</b>
890	Coupling (Pair)		06/2015	TBD	"C" Dolly Coupling - currently no direct replacement
890L	Coupling (Left)				Left-side only (890)
890R	Coupling (Right)				Right-side only (890)
890C	Coupling (Pair)		06/2015	TBD	"C" Dolly Coupling - currently no direct replacement
890CL	Coupling (Left)				Left-side only (890C)
890CR	Coupling (Right)				Right-side only (890C)